

2017 INFINITI QX70 AWD

VIN # JN8CS1MW1HM414702

107009 MILES	Wagon 4 Dr.	3.7 liters V6 Cylinder Engine	All Wheel Drive AUTOMATIC
-----------------	-------------	----------------------------------	------------------------------

INSPECTION LOCATION:
4104 LIGHTSTONE LN, CELINA, TX 75009, USA

EXT: Malbec Black

INT: Graphite



BODY:




GLASS:




PART:



TIRES:



WHEELS:



DISCLOSURES:



INSPECTION DATE:
FEBRUARY 28, 2025 @ 16:41

Vehicle Photos

ORIGINAL INSPECTION





Upload Photos

OPTIONAL

No photo

Interior (0)

No damage

Exterior (5)

LEFT SIDE



Info Severe

COMPONENT	CROPPED PHOTO	DAMAGE TYPE	SEVERITY	REPAIR METHOD
1 Front Left Tire		Is Majorly Worn	Shows Major Wear	Replace
2 Rear Left Tire		Is Majorly Worn	Shows Major Wear	Replace

RIGHT SIDE

Info ● ● ● ● Severe




COMPONENT	CROPPED PHOTO	DAMAGE TYPE	SEVERITY	REPAIR METHOD
3 Rear Right Tire		Is Majorly Worn	Shows Major Wear	Replace
4 Front Right Tire		Is Majorly Worn	Shows Major Wear	Replace

FRONT SIDE



Info ● ● ● ● Severe

COMPONENT	CROPPED PHOTO	DAMAGE TYPE	SEVERITY	REPAIR METHOD
5 Front Bumper Cover		Has Medium Dent - Not Through Paint	> 3 inches	Repair & Refinish

REAR SIDE



Info ● ● ● ● Severe

COMPONENT	CROPPED PHOTO	DAMAGE TYPE	SEVERITY	REPAIR METHOD
-----------	---------------	-------------	----------	---------------

WINDSHIELD

No damage

Tires & Wheels



- Like New
- Good Condition
- Medium Worn
- Major Worn
- Snow Tire

LEFT FRONT

Is Majorly Worn

Shows Major Wear

3/32, 2/32, 1/32

Alloy Wheel

RIGHT FRONT

Is Majorly Worn

Shows Major Wear

3/32, 2/32, 1/32

Alloy Wheel

LEFT REAR

Is Majorly Worn

Shows Major Wear

3/32, 2/32, 1/32

Alloy Wheel

RIGHT REAR

Is Majorly Worn

Shows Major Wear

3/32, 2/32, 1/32

Alloy Wheel

